UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,790,070 B1

DATED

: September 14, 2004

INVENTOR(S) : Donald H. England, II

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2.

Line 48, should read -- truncated conic section tip 11 are typically on opposite ends of --Line 60, should read -- selected point or axis 101. In operation, as seen in FIG. 2, the --

Column 3,

Line 49, should read -- may be located on opposite ends of the locking release --Lines 62-63, should read -- mechanism arm 310 may include a first locking release mechanism arm end portion 311 and a second locking --

Column 4,

Line 18, should read -- spring 415. The plug lock locking mechanism arm 405 may --Line 26, should read -- nism base 410 communicates with the plug lock locking --

Line 33, should read -- disposed within the gain 406. As seen in FIG. 1 in the --

Column 5,

Line 20, should read -- 320 equals the tensile strength of the plug locking mecha---

Signed and Sealed this

Page 1 of 1

Twenty-first Day of December, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office